



Everything is in German



With this migration to later equipment is possible thanks to it's USB-ports. But the chain will not realize.



Also perfectly working, but quite isolated on it's own.



These computers work but have issues with connectors and system batteries (low voltage on battery, connectors break the current from time to time).



These are all dead. Faulty power source probably blew them up.



Boots up promisingly, then jams..

A migrational chain inside Photoshop

